

# Manhole Inspection Summary

# Manhole # S39CC\_014MH

Printed On: 3/9/2009

Page 1 of 4

**Inspection**  Is Incomplete Rating: **3) Fair**

Record Plat: **39CC** Node: **014** Status: **Found**

Insp Date: **12/11/07 12:36 PM**

Incomplete Comments

Crew: 1  
Inspector: **jjoiner**  
Firm: **ATS**

**Location** Address: **1000 bldg ashland ct**

Cross Street: **by dumpster**

**Manhole** Type: **Junction**

Location: **Roadway**

Ground Conditions: **Dry**

Prev. Rehab

Weather: **Dry**

Subject To Ponding: **None**

Comments

**Cover**

Shape: **Circular**

Diameter: **25.** (in.) Length: **0** (in.) Dist A/B Grade: **0** (in.)  
**5**

Type: **Sanitary**

Condition: **Sound**

Cover Material: **Cast Iron**

Properties:  Bolted  Vented  Water Tight  Water Tight Insert

**Frame**

Offset: **0** (in.)

Condition:  Sound  Cracked  Leaks

**Chimney / Frame Adjustment**

Exists Material:

Parged Height: **0** (in.)

Condition:  Sound  Cracked  Root Intrusion  Loose Brick  Deteriorated

Infiltration:  None  Joint  Cracks  Mortar  Roots  Wall

**Corbel**

Material: **Brick**

Parged

Type: **Concentric/Eccentric**

Condition:  Sound  Cracked  Root Intrusion  Loose Brick  Deteriorated

Infiltration:  None  Joint  Cracks  Mortar  Roots  Wall

**Barrel**

Material: **Brick**

Parged

Shape: **Circular**

Diameter: **48** (in.) Length: **0** (in.)

Condition:  Sound  Cracked  Root Intrusion  Loose Brick  Deteriorated

Infiltration:  None  Joint  Cracks  Mortar  Roots  Wall

**Bench**

Exists Material: **Brick**

Parged

Condition:  Sound  Cracked  Root Intrusion  Deteriorated  Leaks  Debris

**Channel**

Material: **Brick**

Parged

Channel Exposure: **Fully Open**

Junc Dist: **1**

nearest .5 ft. Azimuth: **270**

Condition:  Sound  Cracked  Root Intrusion  Deteriorated  Leaks  Debris

**Steps**

Count: **3**

Missing: **0**

**Corroded**

**Surcharge**

**Evidence Of Surcharge**

Depth: **4**

(ft.)

Active Surcharge Present

Location View



Top View



Defect 2



steps

Defect 1



evidence of surcharge

# Manhole Inspection Summary

# Manhole # S39CC\_014MH

Printed On: 3/9/2009

Page 3 of 4

**8 in. Circular Gravity Sewer**  
**Pipe Out @ 12 O'Clock**

**12 O'Clock Outflow**



Pipe Height: **0** (in.) Direct

Pipe Material: **Clay**  Pipe Lined

Invert Depth: **8.80** (ft.) Flow Characteristics: **Slow**

Deposits:  None  Mud  Sludge  Debris  Grease

Silt Depth: **0** (in.) Deposits Extent:

Infiltration: **None** Pipe Seal Cond: **Unknown**

Drop: **None**

Connects To: **Manhole**

Possible Illicit Connection

**8 in. Circular Gravity Sewer**  
**Pipe In @ 3 O'Clock**

**3 O'Clock Inflow**



Pipe Height: **0** (in.) Direct

Pipe Material: **Clay**  Pipe Lined

Invert Depth: **8.70** (ft.) Flow Characteristics: **Slow**

Deposits:  None  Mud  Sludge  Debris  Grease

Silt Depth: **0** (in.) Deposits Extent:

Infiltration: **None** Pipe Seal Cond: **Unknown**

Drop: **None**

Connects To: **Manhole**

Possible Illicit Connection

# Manhole Inspection Summary


Manhole # S39CC\_014MH

Printed On: 3/9/2009

Page 4 of 4

8 in. Circular Gravity Sewer  
Pipe In @ 6 O'Clock

6 O'Clock Inflow



Pipe Height: **0** (in.) Direct

Pipe Material: **Clay**  Pipe Lined

Invert Depth: **8.75** (ft.) Flow Characteristics: **Slow**

Deposits:  None  Mud  Sludge  Debris  Grease

Silt Depth: **0** (in.) Deposits Extent:

Infiltration: **None** Pipe Seal Cond: **Unknown**

Drop: <b>None</b>
-------------------

Connects To: **Manhole**

Possible Illicit Connection

---